

FIG. 1

20045309.01002

2007-05-01 10:45:30




FIG. 2




FIG. 3






FIG. 4

FIG. 5





20045309.011002

FIG. 7A FIG. 7B FIG. 7C FIG. 7D FIG. 7E FIG. 7F





FIG. 8A FIG. 8B FIG. 8C FIG. 8D





20045309 011002

# Localization Uncertainty of 0.1 mm

Without Calibration




FIG. 9A

With Calibration




FIG. 9B

# Localization Uncertainty of 0.5 mm

Without Calibration




Fig. 10A

With Calibration




Fig. 10B

# Localization Uncertainty of 1.0 mm

Without Calibration




FIG. 11A

With Calibration




FIG. 11B

FIG. 12




Fig. 13 A




Image result without SD calibration

Fig. 13B




Image result with SD calibration